



The MHRA have published on the risk of incorrect placement of a central venous catheter and delay to treatment. This is due to a manufacturing problem resulting in:

Decreased length of the catheter. The catheter tip may not reach the desired position during placement.

Catheters with four lumens (instead of five). This may then require additional catheter or extension sets after placement.

**View Alert**

Multicath Expert 5 Lumen central venous catheter medical device alert <http://ctt.ec/31a99+@ivteam> #ivteam

Click To Tweet

**Thank you to our partners for supporting IVTEAM**

